96 Wilkie Way
Proposed Rip-Rap Ditch
Repair/Maintenance

21 Hemlock trees ran parallel to the driveway and ditch at the time quotes were obtained. In an effort to reduce cost, the homeowner has removed 17 of the trees as all contractors indicated the trees would need to be removed prior top the ditch work taking place. The 4 trees that have been left were agreed upon by the selected contractor (Best Value). Stumps will also be left in place as they help form a natural berm.

Typical rip-rap channel/ditch detail. Rock size will match what was recently placed by the Town at the ditch entrance into 96 Wilkie Way



