

Pic 1- Original deck built at time of house construction, in compliance with setbacks



Pic 2- New deck and fence built without permits, deck does not meet setbacks.



Pic 3- Street view of slope on Turnpike Rd, 188 Ashworth on left side of pic.